



# EZ-FILL Software Update

SB165

May 30<sup>th</sup>, 2018

**PRODUCT NAME: EZ-FILL**

**AFFECTED PART NUMBER: 610-00063 AND 610-00063-001**



Figure 1: H-Bridge Module  
610-00063/610-00063-001

Hale is updating the EZ-Fill software to version 1.1, and all units in the field using an H-Bridge Module (Figure 1) will need to be updated to this latest version. Software release 1.1 sets the 3-way valve port to the tank to close position when not in use instead of in the open position. This prevents the foam tank from draining. The H-Bridge Module is only used with the newer SmartTOUCH controller (Figure 2), and not the recently discontinued switch (Figure 3).



Figure 2: SmartTOUCH Controller  
610-00062-000/610-00062-003




Figure 3: 111602/111925 Switch

## OPERATING RECOMMENDATIONS

There are no changes to the recommended installation and end-user operation of this product.

## SOLUTION

Customers with H-Bridge Module part number 610-00063 or 610-00063-001, with version 1.0, can contact customer service to have them returned and updated to version 1.1. The software version can be found on the Class1 label, affixed on the rear of each H-bridge Module, as seen in Figure 4.




Figure 4: H-Bridge Module label

## EFFECTIVITY

May 3<sup>rd</sup>, 2018